	Approved For Releas	e 2006/12/27 : CIA-RDP	75B00159R0004001	00051-1	<b>ε</b> ξ
\$ . T	C. Carlotta	CAS CLASSIFIED B		and the second s	on ongo til etymenty. Kanadaka akasmi dales
PASS.	9725 Z 18 FEB 66		1 Englaces		nergy artists wasterproperties
		SECR	ET STATE	132	Programme (CAS)
grap and map dig ; 8 martin Monata	na nikolaga – mendalaping mengenjunggan daping bebagain panggan kenanggan Libanggan panggan kenanggan pengangan panggan panggan panggan panggan panggan panggan panggan panggan panggan Libanggan panggan pang	as Anglin na Shak ar nagar angkar ngandigan nagan naganar ang ay ani na ngan <mark>asan nahahiping</mark> shinang shipalan Shakin - Shinashin Shipalan a Shina (dan naga nakamar da Shakin anaganar) na baka Shina Shinashina ang ang ang		3	encentration interpretation (in an
<b>10</b>	DIRECTOR		Programme Company of the Company of		ec natureereane
FODN P	9		S S	25	X1 Francisco
AGUIGN	3		Service Control	PRIORITY	
(EXE)	\$	25X1	The same of	25X1	A TRANSPORTER
		25X1			E
	TOR: 0814Z 18 FEB	66	0SA 1-20	IN 8893	17
	PRIORITY	PRIORITY	Supplement of the programmer and the contract and the supplement of the contract and the co	West of the second	San Carlotte Control of the Control
	FROM			25	X1
	REF A:	$\neg$		25	X1 .
	REF B:		•	→ • · · · · · · · · · · · · · · · · · ·	
	SUBJECT STATUS	TEPORT 372 ACCIE	ENT.	•	
$\odot$	1. TEAM DID NO	RETURN TO ACCIDE	ENT SITE 18 FEE	S SINCE MAJOR	
	PORTION OF MORNING	UTILIZED IN COORD	INATING	POSITION RE25	X1
	WHETHER OR NOT	DESIRED EXPEDITED	ACTION. IMM	EDIATELY 25	X1
	AFTER POSITION EST	ABLISHED TEAM DEPA	ARTED FOR	<b>B UT</b> 25	X1
:	G-47 GROUND ABORTER	AND REPAIRS OR F	REPLACEMENT AL	RCRAFT COULD	
	NOT BE PROVIDED IN	SUFFICIENT TIME 1	O MAKE EFFECT	IVE USE OF	
	REMAINING DAY LIGHT	HOURS AT SITE.	TEAM NOW SCHE	DULED TO DEPART	
	EARLY MORNING	19 FEB. FOLLOWIN	NG ACTIONS ARE	PLANNED: 25	X1.
; ;	(A) BEGIN CLEARING	AWAY BRICK, CEMEN	T, AND RUBBLE	FROM BENEATH,	
	ON, AND AROUND AIR	CRAFT.	·	HAVE 25	X1
	BEEN MADE AVAILABLE	E AND WILL BE UTIL	IZED PER	INSTRUCTIONS. 25	X1
	(B) ADDITIONAL PHO	TOS WILL BE TAKEN.	(C) DEPEND	ING UPON	
	ACCESSIBILITY, FUE	L, OIL, HYDRAULIC	FLUID, AND OX	YGEN SAMPLES	
	(CONT'D)			OROUP : OROU : O	
	enger engely matika i general matika indika i	SECI Than the results	RET		

$\mathcal{L}$ .							
IN 88935) S E C R E T	PAGE 25x1						
WILL BE TAKEN. (D) UNTIL CLEAN UP IS ACCOMPLISHED IMPOSS	IBLE						
TO REMOVE CLASSIFIED SYSTEMS AND EQUIPMENT. PRESENTLY PLAN	N						
TO LEAVE EQUIPMENT INSTALLED AS IS UNDER GUARD AND REEVALUA	ATE						
FEASIBILITY OF ATTEMPTING REMOVAL PRIOR TO MOVING AIRCRAFT.	•						
APPEARS NOW THAT BEST POSITION MAY BE TO REMOVE SYSTEMS AFT	l ER						
AIRCRAFT FUSELAGE RETURNED (E) REQUIREMENTS AND	25X1						
AVAILABILITY OF SALVAGE EQUIPMENT FROM	25X1						
WILL BE ESTABLISHED. OTHER EQUIPMENT WILL BE IDENTIFIED AN	AD .						
MOVED FROM (F) LOCATION AND IDENTIFICATION OF ADDIT	TIONAL 25X1						
WITNESSES AT INCLUDING BRIEF OR TR	RANSCRIPT 25X1						
OF UHF TRANSMISSIONS ON	25X1						
2. GENERAL CLEANUP IN AREA WILL REQUIRE APPROXIMATELY (	ONE						
DAY. AFTER CLEANUP AIRCRAFT WILL BE RETAINED IN PRESENT CO	ONFIGURATION						
UNTIL VIEWED BY INVESTIGATION TEAM. WILL ATTEMPT TO TAKE O	CONCERNED						
TEAM MEMBERS FROM FOR VIEW OF S	SITE 25X1						
ON SUNDAY AFTERNOON AND RETURN, IF THEIR ARRIVAL TIME PERMI	ITS.						
SALVAGE OPERATIONS COULD THEN COMMENCE ON MONDAY AND PROBAB	BLY						
BE COMPLETED TUESDAY. DELAYING THE ABOVE ACTIONS UNTIL TEA	4 M						
ARRIVES WOULD PROBABLY EXTEND COMPLETION OF SALVAGE UNTIL	T.						
LEAST NEXT THURSDAY.							
3. HAVE REQUESTED BY SEPARATE MESSAGE LATEST AND	25X1						
WRIGHT PATTERSON FUEL REPORT ON BATCH 41A WHICH WAS USED							
EXCLUSIVELY FROM 4 FEB THROUGH 16 FEB.							
A CANCER OF DEDODER AND MENO MENO							

4. CAUSES OF REPORTED OVER TEMP WHICH LEAD TO SHUT DOWN REMAIN UNKNOWN AT THIS TIME. ALSO HAVE NO FACTUAL INFO TO SUPPORT WHETHER (CONTOD)

SECRET

(IN 88935)	SE	CRET	25X1 PAGE -3-					
OR NOT ANY OTHER SYM	PTOMS WERE NOTE	D. INSPECTION	AND/OR TDR					
OF ENGINE AND ACCESS	ORIES SHOULD PR	OVIDE ANSWERS I						
DETERIOTATION OF WEA	THER AT	AFTER FIELD	WAS REPORTED 25X1					
"IN SIGHT AND GOING	CHANNEL ONE" PR	OBABLY CAUSED F	TILOT TO					
DIVERT TO	REASON FOR AT	TEMPTED FLAMED	OUT APPROACH 25X1					
DOWN WIND AT	IS UNKNOWN.	DISCUSSION WIT	25X1					
TOWER PERSONNEL MAY SHED LIGHT ON THIS POINT.								
5. NAMES OF CASU	ALTIES AND FATAI	LITIES WITH FAM	ILLY ASSOCIATION					
WILL BE VERIFIED AT	THE SCENE NEXT	VISIT. PROPERT	Y DAMAGE WILL					

END OF MESSAGE

ALSO BE FURTHER IDENTIFIED.

SECRET